

B211090339 B21029
 PDR ADDCK 05000277
 R PDR

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH SEPTEMBER, 1982

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
 ENGINEER-IN-CHARGE
 NUCLEAR SECTION
 GENERATION DIVISION-NUCLEAR

TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (2)	METHOD OF SHUTTING DOWN REACTOR (3)	LICENSEE EVENT REPORT #	SYSTEM CODE (4)	COMPONENT CODE (5)	CAUSE AND CORRECTIVE
									ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)
 F - FORCED
 S - SCHEDULED

(2)
 REASON
 A - EQUIPMENT FAILURE (EXPLAIN)
 B - MAINTENANCE OR TEST
 C - REFUELING
 D - REGULATORY RESTRICTION
 E - OPERATOR TRAINING + LICENSE EXAMINATION
 F - ADMINISTRATIVE
 G - OPERATIONAL ERROR (EXPLAIN)
 H - OTHER (EXPLAIN)

(3)
 METHOD
 1 - MANUAL
 2 - MANUAL SCRAM.
 3 - AUTOMATIC SCRAM.
 4 - OTHER (EXPLAIN)

(4)
 EXHIBIT G - INSTRUCTIONS
 FOR PREPARATION OF DATA
 ENTRY SHEETS FOR LICENSEE
 EVENT REPORT (LER)
 FILE (NUREG-0161)

(5)
 EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR
TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (3)	METHOD OF SHUTTING DOWN REACTOR (3)	LICENSEE EVENT REPORT #	SYSTEM CODE (4)	COMPONENT CODE (5)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A "2A" MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

(3)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR

TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS)	REASON (2)	METHOD OF SHUTTING DOWN REACTOR (3)	LICENSEE EVENT REPORT #	SYSTEM CODE (4)	COMPONENT CODE (5)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

(3)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR

TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (3)	METHOD OF SHUTTING DOWN REACTOR (4)	LICENSEE EVENT REPORT #	SYSTEM CODE (5)	COMPONENT CODE (6)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

(3)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M.ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR

TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (3)	METHOD OF SHUTTING DOWN REACTOR (3)	LICENSEE EVENT REPORT #	SYSTEM CODE (4)	COMPONENT CODE (5)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER(EXPLAIN)

(3)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR

TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS)	REASON (2)	METHOD OF SHUTTING DOWN REACTOR (3)	LICENSEE EVENT REPORT #	SYSTEM CODE (4)	COMPONENT CODE (5)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

(3)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR
TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (3)	METHOD OF SHUTTING DOWN REACTOR (4)	LICENSEE EVENT REPORT #	SYSTEM CODE (5)	COMPONENT CODE (6)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A *2A* MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON

A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

(3)

METHOD

1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M.ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR
TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (3)	METHOD OF SHUTTING DOWN REACTOR (3)	LICENSEE EVENT REPORT #	SYSTEM CODE (4)	COMPONENT CODE (5)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER(EXPLAIN)

(3)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M.ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR
TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (3)	METHOD OF SHUTTING DOWN REACTOR (3)	LICENSEE EVENT REPORT #	SYSTEM CODE (4)	COMPONENT CODE (5)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

(2)

(3)

(4)

F - FORCED
S - SCHEDULED

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR

TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (3)	METHOD OF SHUTTING DOWN REACTOR (4)	LICENSEE EVENT REPORT #	SYSTEM CODE (5)	COMPONENT CODE (6)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

(3)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR

TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (3)	METHOD OF SHUTTING DOWN REACTOR (4)	LICENSEE EVENT REPORT #	SYSTEM CODE (5)	COMPONENT CODE (6)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820917	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

(3)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 277

UNIT NAME PEACH BOTTOM UNIT 2

DATE OCTOBER 26, 1982

REPORT MONTH SEPTEMBER, 1982

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR

TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (2)	METHOD OF SHUTTING DOWN REACTOR (3)	LICENSEE EVENT REPORT #	SYSTEM CODE (4)	COMPONENT CODE (5)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8	820903	F	20.9	B	1	NA	HC	HTEXCH	SHUTDOWN TAKEN TO REPAIR A '2A' MOISTURE SEPERATOR DRAIN TANK LEAK.
9	820910	F	15.7	G	1	NA	SA	VALVEX	SHUTDOWN TAKEN AFTER THE OUTER SERVICE AIR VALVE TO THE DRYWELL WAS FOUND OPEN.
10	820912	S	00.0	H	4	NA	RC	ZZZZZZ	LOAD REDUCTION FOR THE ADJUSTMENT OF THE CONTROL ROD PATTERN.
			36.6						

(1)

F - FORCED
S - SCHEDULED

(2)

REASON
A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

(3)

METHOD
1 - MANUAL
2 - MANUAL SCRAM.
3 - AUTOMATIC SCRAM.
4 - OTHER (EXPLAIN)

(4)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

(5)

EXHIBIT I - SAME SOURCE