

REGIONAL REGION  
ATLANTA, GEORGIA



NOV 8 3:01

November 3, 1982  
L-82-484

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2  
Docket No. 50-389, 50.55(e), 82-014  
VALVES WILL NOT RESPOND TO COMMAND SIGNALS

On June 30, 1982, Florida Power and Light Co. (FPL) notified Region II Office of Inspection and Enforcement, in accordance with the requirements of 10 CFR 50.55(e) of a potential deficiency regarding the failure of reactor shutdown cooling bypass valves to respond to command signals. FPL is still reviewing this problem and will submit a final report by November 30, 1982.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

REU/sms

cc: Director of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

OFFICIAL COPY

IE 27

8211100250 821103  
PDR ADOCK 05000389  
S PDR