## LICENSEE EVENT REPORT

	EIGENGEE EVENT HEFORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	1   L   D   R   S   3   2   0   0   -   0   0   0   0   -   0   0
O I	SOURCE L 6 0 5 0 0 0 0 2 4 9 7 1 0 1 5 8 2 8 1 0 2 6 8 2 9
0 2	During steady state operation while conducting DOS 1500-3, CCSW Pump test, the sub-
0 3	marine door to the CCSW pump vault was found open. (Tech. Spec. 3.5.L.1) Safety
0 4	significance was minimal since the CCSW system was operable. No effect on public
0 5	health and safety. First occurrence of this type.
0 6	
0 7	
7 8	9 SYSTEM CAUSE CAUSE COMP VALVE
0 9	CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	TO REPORT NUMBER 2 23 23 24 23 24 25 27 27 28 28 29 29 29 29 29 29 29 29 29 29 29 29 29
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER SUPPLIER MANUFACTURER X 9 9 9 9 9 3
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	Cause of the event was due to personnel error in that contractor personnel failed to
11	close the door. The door was immediately closed. Personnel involved were reminded
1 2	to keep the door closed. The requirement to check the CCSW vault door is contained
1 3	in the operators roundbook which is performed once per shift.
14	<u></u>
15	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 31 Operating Surveillance
	CTIVITY CONTENT 12 13 44 45 46 80  ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8	2 (33) Z (34) N/A
1 7	NUMBER   TYPE   DESCRIPTION (39)   N/A
1 3	NUMBER DESCRIPTION 41 N/A
8	
1 9	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  N/A
1 9	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  N/A  PUBLICITY 821026
1 9	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION N/A  9 10 SOLUTION N/A