(7.77) LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) CONTROL BLOCK: 10 10 10 10 1- 10 10 3 LICENSE NUMBER CON'T L 6 0 15 10 10 10 12 16 17 70 11 10 10 16 18 12 18 11 11 0 1 5 1 8 1 2 19 0 1 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During an audit, it was noted that System 21 loop split modification procedures 0 2 failed to require posting of a fire watch during maintenance and also failed to re-0 3 quire performance of "Fire Barrier Penetration Seals Post Maintenance Inspection," 0 4 SR 5.10.4.b-X. This is contrary to the requirements of Fort St. Vrain LCO 4.10.4 and 0 5 is reportable per AC 7.5.2(b)3. Related occurrence is RO 77-45. No affect on public 0 6 health or safety. COMP VALVE SYSTEM CAUSE COMPONENT CODE SUBCODE CODE CODE SUBCODE D D (12 OCCURRENCE REVISION SEQUENTIAL REPORT NO. REPORT NO. CODE TYPE LER RO 0] REPORT NUMBER COMPONENT NPRD-4 PRIME COMP. ATTACHMENT SUBMITTED HOURS (22) MANUFACTURER FORM SUB. SUPPLIER Z | 9 | 9 | 9 (26) Y (23) N (24) 0 0 0 0 0 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [Controlled Work Procedure Manual (CWPM) was inadequate in specifying the requirements 1 0 of LCO 4.10.4 and SR 5.10.4. The CWPM is being revised to clarify fire barrier penetration seal requirements. Future corrective action will include identification and inspection of existing fire barrier penetration seals, and inclusion of all seals in SR 5.10.4.A-A. 1 4 METHOD OF FACILITY (30) DISCOVERY DESCRIPTION (32) OTHER STATUS DISCOVERY % POWER NFSC Audit C (31) 0 0 0 (29) 9 10 ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) OF RELEASE N/A Z (34) Z (33) 80 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER (37) Z (38) N/A 10 0 PERSONNEL INJURIES DESCRIPTION (41) NUMBER (40) 8211190184 821105 PDR ADOCK 05000267 LOSS OF OR DAMAGE TO FACILITY (43) PDR DESCRIPTION (42) N/A NRC USE ONLY PUBLICITY DESCRIPTION (45) N 44 N/A

NAME OF PREPARER Charles Full

PHONE: (303) 785-2224