LICENSEE EVENT REPORT

5 1 1 1	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	G A E I H 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 2 1 7 1 0 0 8 8 2 8 1 1 0 0 4 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 On October 8, 1982, with the unit in the run mode at 90% power an oil
0 3	pump trip signal was received for the B recirculation pump. The redund-
0 4	ant oil pump failed to auto start and this caused the B recirculation
0 6	pump to trip. This is a violation of administrative control per Tech.
0 6	Specs. Section 6.9.1.9.b. The health and safety of the public were not
0 7	[affected by this non-repetitive event.
08	9 80
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	LER/RO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN COMPONENT
	TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER LT 18 2 19 19 19 19 19 19 19 19 19 19 19 19 19
10	Investigation revealed the supply breaker to the operating oil pump had
11	been placed in the off position. The breaker was reset and the B recir-
112	culation pump was returned to service. The redundant oil pump's failure
1 3	to auto start is currently under investigation.
1 4	9 80
	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA I A 31 Operator Observation 80
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA NA NA NA NA NA NA NA NA N
1 7	PERSONNEL EXPOSURES NUMBER 17 PE DESCRIPTION 39 NA 9 11 12 13
1 8 7 8	PERSONNEL INJURIES NUMBER 10 10 10 40 DESCRIPTION 1 NA PDR ADDCK 05000321 9 11 12 80
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA 9 10 80
2 0	PUBLICITY ISSUED DESCRIPTION 45 NA NA NA 68 69 80 5
	NAME OF PREPARER H. L. Sumner - Supt. Plt. Eng. Serv. PHONE 912-367-7851