



LER No.: 50-321/1982-089  
Licensee: Georgia Power Company  
Facility: Edwin I. Hatch  
Docket #: 50-321

NARRATIVE REPORT  
for LER 50-321/1982-089

On October 26, 1982, with the unit shutdown for refueling, augmented In Service Inspections (ISI) were performed on selected service sensitive welds as required by NuReg 0313, Revision 1. Seven code rejectable linear indications were discovered during ultrasonic examinations of shop fabricated welds on the RHR suction line from Recirc. Loop "B". The unit has been placed in a limiting condition for operation (LCO) as per Tech. Specs. Section 3.6.k. The health and safety of the public were not affected by this non-repetitive event.

The cause of this event has not been determined. An engineering investigation and evaluation will determine the cause and determine the requirements necessary to correct the problem and prevent recurrence. As per Tech. Specs. Section 3.6.k, the unit will remain at cold shutdown until an engineering decision can be reached and the problem resolved.