



**Florida  
Power**  
CORPORATION

November 12, 1982  
#3F-1182-11  
File: 3-0-3-a-1

REGIONAL REGIONAL  
NOV 15 AID: 34

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement  
101 Marietta St. N.W., Suite 3100  
Atlanta, Ga. 30303

Subject: Crystal River Unit 3  
Docket No. 50-302  
Operating License No. DPR-72  
Licensee Event Report No. 82-064

Dear Mr. O'Reilly:

Enclosed please find Licensee Event Report No. 82-064 and the attached supplementary information sheet, which are submitted in accordance with Technical Specification 6.9.1.8.b.

This report is a follow-up to our report to Mr. J. P. O'Reilly dated November 1, 1982. In the initial report, this event was determined to be contrary to Technical Specification 3.6.1.2. As this event occurred due to failure to prove operability following maintenance on a containment isolation valve, this event is being reported under Technical Specification 3.6.3.1.

Should there be any questions, please contact this office.

Very truly yours,

*P. Y. Baynard*

P. Y. Baynard  
Assistant to Vice President  
Nuclear Operations

PGH/mlg

Enclosure

8211170310 821112  
PDR ADOCK 05000302  
S PDR

OFFICIAL COPY  
IE 22

cc: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555