



Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

R. W. KRIEGER
STATION MANAGER

TELEPHONE
(714) 398-6255

January 18, 1991

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-361
Supplemental Report
Licensee Event Report No. 90-015, Revision 1
San Onofre Nuclear Generating Station, Unit 2

Reference: Letter, R. W. Krieger (SCE) to USNRC Document Control Desk, dated
January 3, 1991

The referenced letter provided Licensee Event Report (LER) No. 90-015, for a condition involving an auxiliary feedwater pump (AFWP) support system piping mis-assembly. As indicated in the original LER, the results of our investigation, including the root cause and corrective actions to prevent recurrence, have been provided in this supplemental LER. This event was originally reported as a condition prohibited by the plant's Technical Specifications. However, based on our current analysis of this event, it is concluded that operation of this AFWP support system is not required to meet design basis requirements. Therefore, the piping mis-assembly did not render the AFWP inoperable. However, because installation of the support system was performed pursuant to a FTOL Condition, and because we recognize the programmatic implications of this event, this information is being submitted as a voluntary LER. Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

If you require any additional information, please so advise.

Sincerely,

Enclosure: LER No. 90-015-01

cc: C. W. Caldwell (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. B. Martin (Regional Administrator, USNRC Region V)
Institute of Nuclear Power Operations (INPO)

9101230308 910118
PDR ADOCK 05000361
S PDR

23104