


DO



December 26, 1990

LTR:

BYRON 90-1219

FILE:

3.11.0320

Mr. A. Bert Davis
Regional Administrator
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
Glen Ellyn, IL 60139

SUBJECT:

Commonwealth Edison Byron Unit 2 Steam Generator Eddy Current

Examination During the Cycle 2 Refueling Outage

Dear Mr. Davis:

Please find attached a report of the Byron Unit 2 Steam Generator examination performed during the Cycle 2 refueling outage of September-November of 1990. This report is being submitted to you in compliance with the requirements of Mandatory Appendix IV of Section XI of the ASME Boiler and Pressure Vessel Code, 1983 Edition through Summer 1983 A denda in accordance with Byron Technical Specification 4.0.5.

If there are any questions, please contact Mr. J. R. Smith at Byron Station at (815) 234-5441 extension 2847.

R. Plenlewicz Station Manager

Byron Nuclear Power Station

RP/JRS/kc

cc: M. Wallace/K. Graesser (w/o attachment)

P. Johnson (w/o attachment)

K. Kofron (w/attachment)

R. Tamminga (w/attachment)

J. Blomgren (w/attachment)

T. Schuster (w/attachment )

J. Hendricks (w/attachment - 2 copies)

JAN 1 7 1991

(3017z/0060z/122690) 9101240226 901226 PDR ADOCK 05000455 PDR