



November 15, 1982
L-82-507

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

NOV 19 11:00
REGION II
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2
Docket No. 50-389, 10 CFR 50.55(e), 82-021 /
Incorrect RPS Low Flow Input Signal

On October 13, 1982, Florida Power and Light Company (FPL) notified the Region II Office of Inspection and Enforcement in accordance with the requirements of 10 CFR 50.55(e) of a potential deficiency regarding incorrect RPS low flow input signals. FPL is still reviewing this problem and will provide a final report by December 12, 1982.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems and Technology

REU/jas

cc: Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

OFFICIAL COPY
IE 27

8211230056 821115
PDR ADDCK 05000389
S PDR