



November 15, 1982  
L-82-506

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2  
Docket No. 50-389, 10 CFR 50.55(e), 82-020  
Lack of Documentation on Class I and II Bolts and Nuts

NOV 19 11:00  
REGION II  
ATLANTA, GEORGIA

On October 13, 1982, Florida Power and Light Company (FPL) notified the Region II Office of Inspection and Enforcement in accordance with the requirements of 10 CFR 50.55(e) of a potential deficiency regarding the lack of documentation on Class I and II bolts and nuts. FPL is still reviewing this problem and will submit a final report by December 22, 1982.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

REU/jea

cc: Director of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

OFFICIAL COPY  
IE 27

8211230194 821115  
PDR ADOCK 05000389  
S PDR