LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 0 0 0 0 -0 3 0 0 -0 0 CON'T (7)[1] 1 0 4 8 15 10 10 10 14 6 0 1 SOURCE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During a recent Commission audit of LCOs, it was discovered that an action statement was entered per T.S.3.7.7 on July 30, 1982, and a required special report pursuant to | 0 3 T.S.6.9.2 was not filed. This had no effect on the health and safety of the public 0 4 and did not constitute a threat to plant safety. SYSTEM CAUSE CAUSE COMP VALVE SUBCCCC Z 15 Z (16) Z A (13) Z Z Z (14) A REVISION OCCURRENCE SEQUENTIAL REPORT EVENT YEAR REPORT NO CODE TYPE 0 1016 01 1 T NUMBER COMPONENT MANUFACTURER Z 19 19 19 ATTACHMENT SUBMITTED NPRD-4 FORM SUB PRIME COMP. HOURS Z (21) 0 1010 21 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The action statement of T.S.3.7.7 was entered due to incomplete construction of safety related cables. An hourly firewatch was established, however, an incident report was not filed as required by plant procedures. This resulted in the special report required by T.S.3.7.7 not being filed. This is being submitted as a interim report per T.S.6.9.1.12.b. 80 METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32) OTHER STATUS % POWER C (31) NRC Inspection 0 0 0 0 80 ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED OF RELEASE NA Z (34) Z (33) 80 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE 0 (37) Z (38) NA 0 0 80 8211230244 821117 PDR ADDCK 05000416 DESCRIPTION (41) PDR NA 0 0 (40) 80 LOSS OF OR DAMAGE TO FACILITY DESCRIPTION NA Z (42) PUBLICITY NRC USE ONLY DESCRIPTION (45) N (44) NA NAME OF PREPARER Original signed by M. Scott Freeman

PHONE -

SUPPLEMENTARY INFORMATION TO LER 82-106/01 T-0

Mississippi Power & Light Company Grand Gulf Nuclear Station - Unit 1 Docket No. 50-416

Technical Specification Involved: 3.7.7
Reported Under Technical Specification: 6.9.1.12.b

Event Narrative:

During a recent NRC audit of LCO's, it was discovered that an action statement was entered for T.S.3.7.7 on July 30, 1982, and a required special report pursuant to T.S.6.9.2 was not filed.

The LCO was entered due to required fire-protection insulation missing from some safety related cable trays resulting from incomplete construction. An hourly fire-watch was established, however, an incident report was not filed as required by plant procedures. Therefore, the special report required by T.S.3.7.7 was not filed.

This report is intended to comply wich T.S.6.9.1.12.b and T.S.6.9.1.13.b and is written to document noncompliance with T.S.3.7.7. The plant is currently operating under the T.S.3.7.7 action statement. A firewatch is established and work is on going to insulate the cable trays. This is being submitted as a interim report. A followup report will be submitted by January 18, 1983, which will include actions to be taken to prevent recurrence of this problem.

Previous Similar Events:

None.