## LICENSEE EVENT REPORT

	CONTROL BLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	I   L   Z   I   S   2   2   0   0   -   0   0   0   0   -   0   0
0 1 7 8	SOURCE LO 5 0 0 0 0 3 0 4 7 0 9 2 1 8 2 8 1 1 1 5 8 2 9
0 2	During the daily surveillance with Unit 2 in cold shutdown, component
0 3	cooling heat exchanger radiation monitor (2RE 0017) was found failed.
0 4	This violates TS 3.14.1.A.Since the operable redundant monitor
0 5	(ORT PR07) did not detect any rad increases and since the monitor was
0 6	returned to operation within one shift, there were no safety implica-
0 7	tions that would affect the public. There have been no previous LERs.
0 8	90
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
10	LERIRO EVENT YEAR REPORT NO.  17 REPORT   8 2
11	tube (RCS part no. 6S4). The tube was replaced and the monitor return-
1 2	ed to service. No further response is necessary.
1 3	
14	
1 5	9 FACILITY STATUS SPOWER OTHER STATUS OTHER
	CONTENT CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35  Z 33 Z 34 NA  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY 35  NA  44  45  LOCATION OF RELEASE 36  NA  80
1 7	NUMBER 0 37 Z 38 065CRIPTION (39) NA NA
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41  NA  NA  NA
1 9	Coss of OR DAMAGE TO FACILITY (43)   POSSIBLE OF THE PROPERTY   POSSIBLE OF THE POSSIBLE OF THE PROPERTY   POSSIBLE OF THE POSSIBLE OF THE POSSIBLE OF THE PROPERTY   POSSIBLE OF THE POSSIBL
20	PDR ADOCK 05000304 SSUED DESCRIPTION 45 S PDR
	NAME OF PREPARER Valerie S. Williams PHONE 312-746-2084 ext.554 3