	LICENSEE EVENT REPORT Attachment to AECM-82/552 Page 1 of 1
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 EIGENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 1 0 1 9 8 2 8 1 1 1 1 6 8 2 9  SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	During performance of the LPCS Monthly Functional Test, 06-0P-1E21-M-0001, the suction
hoosekeese	
0 3	strainers for the Low Pressure Core Spray Jockey Pumps were discovered to require
0 4	cleaning. To clean the strainers, the Jockey Pump and LPCS Pump Breakers were racked
0 5	out which resulted in LPCS being inoperable per T.S.3.5.1.a.1. Upon completion of
0 6	strainer cleaning, the LPCS system was filled, vented and returned to service. This
0 7	had no effect on the health and safety of the public and did not constitute a threat
0 8	to plant safety.
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
7 8	9 10 11 12 13 18 19 20 SEQUENTIAL OCCURRENCE REPORT REVISION
	17) LER/RO REPORT NO. REPORT NO. LER/RO STATE NO. LER/RO
	ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
	X 13 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 B 1 3 0 26
	33 34 35 36 37 40 41 42 43 44 47  CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	33 34 35 36 37 40 41 42 43 44 47
10	33 34 35 36 37 40 41 42 43 44 47  CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  [The strainers were cleaned and returned to service on October 20, 1982. Presently,
10112	The strainers were cleaned and returned to service on October 20, 1982. Presently, the suppression pool is under going cleaning and the pipes in the suppression pool are
1 0 1 1 2 1 3 1 4 7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  [The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are  being painted which should prevent this recurrence. This is intended as a final  report.
7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  [The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are  being painted which should prevent this recurrence. This is intended as a final  report.
7 8 1 5 7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are  being painted which should prevent this recurrence. This is intended as a final  report.  Apower other status (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  NA B (31) Surveillance Test  STINITY CONTENT 12 13 44 45 46 80
7 8 1 5 7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are peing painted which should prevent this recurrence. This is intended as a final report.
7 8 1 5 7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are  being painted which should prevent this recurrence. This is intended as a final  report.  B B B D B D B D B D B D B D B D B D B
7 8 1 5 7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are  being painted which should prevent this recurrence. This is intended as a final  report.    1
7 8 1 5 7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are  being painted which should prevent this recurrence. This is intended as a final  report.    Description (32)
7 8 1 5 7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are  being painted which should prevent this recurrence. This is intended as a final  report.    1
7 8 1 5 7 8	The strainers were cleaned and returned to service on October 20, 1982. Presently,  The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are leave the suppression pool are personned which should prevent this recurrence. This is intended as a final report.
7 8 1 5 7 8	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  The strainers were cleaned and returned to service on October 20, 1982. Presently,  the suppression pool is under going cleaning and the pipes in the suppression pool are  being painted which should prevent this recurrence. This is intended as a final  report.    Comparison of the strain of the suppression pool are