

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | J | S | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 2 | 7 | 1 | 0 | 1 | 8 | 8 | 2 | 8 | 1 | 1 | 0 | 3 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | On October 18, 1982, during routine shutdown operations, it was discovered that the
03 | shutdown margin calculation had not been performed the previous day as required by
04 | Technical Specification Surveillance Requirement 3.1.1.2. With the failure to
05 | determine the shutdown margin, Action Statement 3.1.1.2 applied. The surveillance
06 | was satisfactorily performed; the event constituted operation in a degraded mode in
07 | accordance with Technical Specification 6.9.1.9.b.
08 | _____

09 | R | B | 11 | A | 12 | A | 13 | X | X | X | X | X | X | 14 | Z | 15 | Z | 16
7 8 9 10 11 12 13 18 19 20
17 | 8 | 2 | 21 | 22 | 0 | 8 | 0 | 23 | 24 | 26 | 27 | 0 | 3 | 28 | 29 | L | 30 | 31 | 0 | 32
18 | H | 19 | Z | 19 | 20 | Z | 21 | 0 | 0 | 0 | 22 | Y | 23 | N | 24 | Z | 25 | Z | 19 | 19 | 19 | 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | The shutdown margin calculation was not performed due to oversight. Personnel
11 | involved in the incident were counseled concerning the Surveillance Requirements for
12 | shutdown margin.
13 | _____
14 | _____

15 | D | 28 | 0 | 0 | 0 | 29 | N/A | 30 | A | 31 | Operator Observation | 32
7 8 9 10 12 13 44 45 46 80

16 | Z | 33 | Z | 34 | N/A | 35 | N/A | 36
7 8 9 10 11 44 45 80

17 | 0 | 0 | 0 | 37 | Z | 38 | N/A | 39
7 8 9 11 12 13 80

18 | 0 | 0 | 0 | 40 | N/A | 41
7 8 9 11 12 80

19 | Z | 42 | N/A | 43
7 8 9 10 80

20 | N | 44 | N/A | 45
7 8 9 10 80

NAME OF PREPARER R. Frahm PHONE 609/935-6000 Ext 3078

8211230445 821103
PDR ADOCK 05000272
S PDR