



ATTACHMENT TO LER # 82-085/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

INVESTIGATION REVEALED THAT THE RECORDER MECHANISM THAT RAISES THE STYLUSES WAS BINDING, THUS CAUSE SOME STYLUSES TO REMAIN IN A SLIGHTLY RAISED POSITION. PARTS TO REPAIR THE RECORDER MECHANISM HAVE BEEN ORDERED AND WILL BE INSTALLED UPON RECEIPT. DURING THE INTERIM, INSTRUCTIONS HAVE BEEN PLACED AT THE RECORDER LOCATION INFORMING THOSE CHANGING THE CHART PAPER OF THIS MECHANISM PROBLEM, AND THAT VERIFICATION OF CORRECT OPERATION FOR EACH STYLUSE IS REQUIRED AFTER THE REPLACEMENT OF CHART PAPER.