LICENSEE EVENT REPORT

그는 그는 것이 가지가 많아 보는 맛이 되었다면 되는 사람들이 되었다면 하는 것이 되었다면 하는 것이 없는 것이 없는데
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M A P P S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 57 CAT 58 5
CON'T O 1 SOURCE L O 5 O - O 2 9 3 7 1 O 1 2 8 2 3 1 1 1 2 8 2 9 7 8 SOURCE SOURCE
On 10/12/82 and 10/13/82, during slutdown conditions, off-site power was lost. The
emergency diesel generators immediately started as per design upon loss of startup
1 transformer with the unit auxiliary transformer de-energized. Station safety related
0 5 equipment functioned as intended during and after the switchover to the diesels.
0 6 These events caused no threat to the public health and safety. The NRC was notified
0 7 via regular telephone. ENS line was out of service.
7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
CODE SUBCODE S
SEQUENTIAL REPORT NO. IT REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE COMPONENT HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. COMPONENT MANUFACTURER X 18 X 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 26 33 34 34 35 36 37 40 41 41 42 43 44 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1] A heavy ocean storm created an accumulation of salt on the switchyard insulators.
Both incoming lines were lost when their breakers opened and could not reclose.
Power was restored when the salt was washed from the insulators and the breakers
1]3 reclosed.
T 1 BO
FACILITY % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 G 28 0 0 0 0 29 NA A 31 Operational Event
7 8 9 10 12 13 44 45 46 80 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA NA NA NA
7 8 9 10 11 44 45 30 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 37 Z 38 NA NA 80
1 8 0 0 0 0 40 NA
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
7 8 9 10 8211290345 821112 30
2 0 N (44) PDR NA
NAME OF PREPARER G. G. Whitney PHONE 617-746-7900