DMB

50-311



DESIGNATED ORIGINAL

Certified By Map

Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 03038

Salem Generating Station

November 24, 1982

Mr. R. C. Haynes Regional Administrator USNRC Region 1 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

REPORTABLE OCCURRENCE-82-136/01P SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the NRC Headquarters on Wednesday, November 24, 1982, advising of a potential reportable occurrence in accordance with IE Bulletin 80-24.

During routine power operation, a small service water leak was discovered inside the Containment Building, on No. 23 Containment Fan Coil Unit. The leak rate was approximately 0.5 gallons per minute, and the leak has been isolated.

An investigation is in progress, and a detailed report will be submitted in the time period specified by IE Bulletin 80-24.

Sincerely yours,

H.J. Sufilen

H. J. Midura General Manager -Salem Operations

RF:ks

CC: Distribution

B211290359 B21124 PDR ADOCK 05000311 S PDR

The Energy People

TE 29