LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK:
7 8	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 1 0 2 5 8 2 8 1 1 1 1 0 8 2 9
0 2	On October 25, 1982, it was discovered that the thermal detectors for the Units 1 & 2
0 3	Iodine Removal Systems and Pressure Relief Systems had not been included in the fire
0 4	detection instrumentation surveillance procedures. Testing of the detectors in
0 5	accordance with Surveillance Requirements 4.3.3.6.1 had not been performed since system
0 6	installation. The testing was subsequently performed satisfactorily; the detectors
0 7	were apparently operable since installation. The event constituted operation in a
0 8	degraded mode in accordance with Technical Specification 6.9.1.9.b.
0 9	SYSTEM CAUSE COMPONENT CODE COMPONENT CODE SUBCODE SUB
	TO LER RO REPORT NO. SEQUENTIAL REPORT NO. CODE TYPE NC.
	ACTION FUTURE TAKEN ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER X 9 9 9 9 26
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	The detectors were omitted from the surveillance procedures due to oversight at the
1 1	time of writing. New procedures have been written and are presently in the review
1 2	process.
1 3	
14	
7 8	FACILITY STATUS OTHER STATUS OF DISCOVERY DESCRIPTION OF Quality Assurance Program
	2 CTIVITY CONTENT 12 13 44 45 46 80 ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 N/A N/A
7 8	9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 0 0 0 37 Z 38 N/A
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	2 42 N/A 8211290494 821110 80
2 0	PUBLICITY ISSUED DESCRIPTION 45 N/A PDR ADDCK 05000272 PDR NRC USE ONLY PDR
7 8	9 10 R. Frahm PHONE 68 69 80 5