LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M D C C N 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 6 TAT 58
CON'T O 1 REPORT L O 0 0 0 0 1 7 7 1 0 1 4 8 2 8 1 1 1 2 8 2 9
0 2 At 1838, during surveillance testing, 11 Refueling Water Tank (RWT) was
inadvertently drained to the Spent Fuel Pool to a level of 455 inches
[0]4] [(T.S. 3.5.4). The valve line-up error was corrected and the RWT filled
o s to greater than 400,000 gallons at 1915.
0 6 Similar events: none.
0 7
0 8 L 7 8 9
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
LER/RO
The cause of this event was that a step was missed during the perfor-
mance of the surveillance test. Corrective action has been to verbally
reinstruct the operator to be more careful in the performance of all
plant procedures and tests. All operators have been informed of this
1 4 event.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 T 5 E (28) 1 0 0 (29) N/A A (31) Operator Observation
7 8 9 10 12 13 44 45 46 80 ACTIVITY CONTENT (SC)
1 6 Z 33 Z 34 N/A N/A N/A 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 0 0 0 0(37) Z (38) N/A
7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41)
1 8 0 0 0 40 N/A 7 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 1 9 Z (42) N/A
7 8 9 10 PUBLICITY BSSUED DESCRIPTION 45 PDR ADOCK 05000317 S PDR ADOCK 05000317 S PDR 68 69 80 5
8 9 10 301-269-4747 0