

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [M][D][C][C][N][2] (2) [0][0] - [0][0][0][0][0] - [0][0] (3) [4][1][1][1][1] (4) [ ] (5)  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CONT  
[0][1] REPORT SOURCE [L] (6) [0][5][0][0][0][3][1][8] (7) [1][0][1][7][8][2] (8) [1][1][1][2][8][2] (9)  
7 8 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
[0][2] During Mode 5 operation at 0105 while performing surveillance testing on  
[0][3] Main Steam Line Isolation Valves (MSIV's), No. 21 MSIV stroked shut in  
[0][4] 12.72 seconds, exceeding the 3.6 second limit of T.S. 4.7.1.5. Although  
[0][5] T.S. 3.7.1.5 is not applicable in Mode 5, it is assumed that the valve  
[0][6] could have been slow to close, had it been stroked shut in Modes 1 - 3.  
[0][7] Similar event: 81-07.

[0][9] SYSTEM CODE [C][D] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [B] (13) COMPONENT CODE [V][A][L][V][E][X] (14) COMP. SUBCODE [F] (15) VALVE SUBCODE [D] (16)  
7 8 9 10 11 12 13 18 19 20  
[17] LER/RO REPORT NUMBER [8][2] (21) EVENT YEAR [ ] (22) SEQUENTIAL REPORT NO. [0][5][0] (24) OCCURRENCE CODE [ ] (25) REPORT TYPE [L] (30) REVISION NO. [0] (32)  
ACTION TAKEN [Z] (18) FUTURE ACTION [X] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS (22) ATTACHMENT SUBMITTED [N] (23) NPRD-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [A] (25) COMPONENT MANUFACTURER [R][3][4][0] (26)  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
[1][0] The cause of the failure of the valve to stroke in the required time has  
[1][1] not yet been determined. Both the actuator and the packing chamber will  
[1][2] be disassembled during the current refueling outage to determine the  
[1][3] specific cause and effect corrective action. A follow-up report will be  
[1][4] submitted upon completion of the inspection.

[1][5] FACILITY STATUS [G] (28) % POWER [0][0][0] (29) OTHER STATUS [N/A] (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION [Surveillance Testing] (32)  
7 8 9 10 12 13 44 45 46 80

[1][6] ACTIVITY CONTENT [Z] (33) RELEASED OF RELEASE [Z] (34) AMOUNT OF ACTIVITY [N/A] (35) LOCATION OF RELEASE [N/A] (36)  
7 8 9 10 11 44 45 80

[1][7] PERSONNEL EXPOSURES NUMBER [0][0][0] (37) TYPE [Z] (38) DESCRIPTION [N/A] (39)  
7 8 9 11 12 13 80

[1][8] PERSONNEL INJURIES NUMBER [0][0][0] (40) DESCRIPTION [N/A] (41)  
7 8 9 11 12 80

[1][9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [N/A] (43)  
7 8 9 10 80

[2][0] ISSUED PUBLICITY [N] (44) DESCRIPTION [N/A] (45)  
7 8 9 10 80

8211290549 821112  
PDR ADOCK 05000318  
S PDR

NRC USE ONLY

NAME OF PREPARER R. L. Wenderlich/P. J. Weir PHONE: 301-269-4776/4871