



Duquesne Light

Nuclear Division
P.O. Box 4
Shippingport, PA 15077-0004

Telephone (412) 456-6000

November 10, 1982
ND1SSI:667

Beaver Valley Power Station, Unit No. 1
Docket No. 50-334, License No. DPR-66
LER 82-044/03L


Mr. R. C. Haynes, Regional Administrator
United States Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Reports are submitted:

LER 82-044/03L, Technical Specification, 3.7.15, Penetration Fire Barriers. This event which occurred on January 28, 1982, is being reported late since a review of the incident has determined that a Licensee Event Report is required to satisfy the reporting requirements of Technical Specification 6.9.1.9.b. Due to an oversight, this information was unintentionally omitted from LER 82-004/03L which addressed the events immediately preceeding this incident.

Very truly yours,


W. S. Lacey
Superintendent

Attachment

8211290552 821110
PDR ADOCK 05000334
S PDR

IER2

Mr. R. C. Haynes
November 10, 1982
ND1SS1:667
Page 2

cc: Director Of Management & Program Analysis
United States Nuclear Regulatory Commission
Washington, D. C. 20555

J. Hultz, Ohio Edison

Director, Office of Inspection and Enforcement Headquarters
United States Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Peter Tam, BVPS Licensing Project Manager
United States Nuclear Regulatory Commission
Washington, D. C. 20555

W. M. Troskoski, Nuclear Regulatory Commission, BVPS Site Inspector

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator, Toledo Edison

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Arthur Alford, Stone & Webster/Boston