LICENSEE EVENT REPORT

CONTRC BLOCK: -
IN JOCP 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
O 1 SOURCE 60 51 DOCKET NUMBER 68 60 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
It was discovered on October 12, 1982 that Emergency Service Water (ESW)
pump 52A had been declared inoperable during testing and later rendered
inoperable for maintenance. This constitutes operation in a degraded
mode permitted by a limiting condition for operation as specified in
Tech Specs, para. 3.4.C.4. The safety significance of the event is
minimal due to the fact that the redundant pump in the system was
operable. This event is reportable per Tech Specs, para. 6.9.2.b.2.
SIB TO DE SUBCODE COMPONENT CODE SUBCODE SUBCO
17) REPORT 8 2
TAKEN ACTION ON PLANT METHOD HOURS (27) SUBMITTED FORM SUB SUPPLIER MANUFACTURER LE IB X 19 Z 20 Z 20 J 0 0 0 0 Y 20 N 20 A 25 B 5 8 0 0
CAUSE DESCRIPTION AND CORNECTIVE ACTIONS (2) The cause was attributed to improper impeller clearance setting. The
The cause was attributed to improper impeller clearance setting. The
pump 52A was removed from service and the impeller clearance adjusted.
The pump tested satisfactorily and was returned to service. Procedure
708.1.002 was revised to more clearly detail impeller clearance adjust.
STATUS SPOWER OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) [15] [E] (28) [0] [6] [6] (29) NA B (31) Surveillance Test
7 1 2 10 12 13 14 46
ACTIVITY (30) RELEASED OF RELEASE AMOUNT OF ACTIVITY (30) NA PERSONNEL EXPOSURES NA NA NA NA NA NA NA NA NA N
NA NAMBER OESCRIPTION (39)
PETISONNEL INJURIES NUMBER DESCRIPTION 41
NA NA
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
PUBLICITY NAC USE ONLY
[2 6 IN (64)] NA
NAME OF PREPARER Michael J. Fitzgerald PHONE (609) 971-4896