Maine Yankee Reportable Occurrence No. 82-030/01T-1

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONTINUED)

The eddy current testing required by Technical Specification 4.10 will be modified to concentrate on the tube zone known to experience this defect.