NRC FOI (7-77)	U. S. NUCLEAR REGULATORY COMMISSION
•.	CONTROL BLOCK:
	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
CON'T	REPORT L 6 0 5 0 0 0 3 6 6 7 1 0 1 8 8 2 8 1 1 1 6 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	Factory Representatives who intended to perform preventive maintenance on the "10
03	D/G" were inadvertently escorted into the "2C" D/G room where they engaged the over-
0 4	speed trip (D/G not running). With "2C/DG" inop T.S. 3.8.1.1.b was not satisfied;
0 5	it was immediately reset. Public health and safety were not affected by this non-
06	repetitive event.
0 7	L
08	9
0 9 7 8	SYSTEM CODE B B B CODE CODE CODE CODE CODE CODE CODE CODE
	Image: Description and corrective actions Image: Description and corrective action a
10	The trip was due to personnel error: an escort led the factory reps to the wrong
III	D/G room, and the reps tripped the D/G while the escort was checking for clearance
12	Ltags (to ensure the D/G had been properly removed from service). The escort was
13	admonished as to the responsibilities he has when acting as an escort.
14	80
1 5	FACILITY STATUS Nethod of Discovery Discovery Discovery Discovery Description 32 E 28 1 0 0 9 NA A 31 Trip of "2C" D/G 32
	9 CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 9 VERSONNEL EXPOSURES AMOUNT OF ACTIVITY (35) 10 11 VERSONNEL EXPOSURES AMOUNT OF ACTIVITY (35) 10 11 11 12 13 14 44 45 46 16 10 10 10 10 10 10 10 10 10 10
17 78	PERSONNEL INJURIES
18	
1 8	9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION (43)
2 8	Z 42 NA 9 10 8211290721 821116 80 PUBLICITY 45 PDR ADDCK 0500000 NRC USE ONLY
20	PUBLICITY ISSUED DESCRIPTION 45 PDR ADOCK 05000366 NA 5 PDR 68 69 80 5
	NAME OF PREPARER S.B. Tipps PHONE (912) 367-7851