

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P | A | B | V | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5

8 9 | LICENSEE CODE 14 15 | LICENSE NUMBER 25 26 | LICENSE TYPE JO 57 CAT 58

CON'T

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 4 | 7 | 1 | 0 | 1 | 7 | 8 | 2 | 8 | 1 | 1 | 0 | 5 | 8 | 2 | 9

8 | REPORT SOURCE 60 61 | DOCKET NUMBER 68 69 | EVENT DATE 74 75 | REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a routine surveillance on 10/17/82, the 1A Containment Vacuum

0 3 | Pump (CV-P-1A) was discovered to have a broken drive belt. The pump

0 4 | was declared inoperable at 0345 hours while power operation continued in

0 5 | accordance with the action statement of Technical Specification 3.6.5.2.

0 6 | The health and safety of the public was not jeopardized since the

0 7 | redundant vacuum pump remained operable.

0 8 | \_\_\_\_\_ 80

0 9 | SYSTEM CODE [S] [A] (11) | CAUSE CODE [E] (12) | CAUSE SUBCODE [F] (13) | COMPONENT CODE [P] [U] [M] [P] [X] [X] (14) | COMP. SUBCODE [G] (15) | VALVE SUBCODE [Z] (16)

(17) LER/RO REPORT NUMBER [8] [2] (21) (22) | SEQUENTIAL REPORT NO. [0] [4] [5] (24) (26) | OCCURRENCE CODE [0] [3] (28) (29) | REPORT TYPE [L] (30) | REVISION NO. [0] (32)

ACTION TAKEN [A] (18) | FUTURE ACTION [Z] (19) | EFFECT ON PLANT [Z] (20) | SHUTDOWN METHOD [Z] (21) | HOURS [0] [0] [0] [0] (37) (40) | ATTACHMENT SUBMITTED [Y] (23) | NPRO-4 FORM SUB. [N] (24) | PRIME COMP. SUPPLIER [N] (25) | COMPONENT MANUFACTURER [G] [0] [4] [6] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The Containment Vacuum pump drive belt failure was most likely due to

1 1 | aging, which caused belt to crack and break. The vacuum pump was

1 2 | returned to service on 10/18/82 after the broken drive belt was replaced.

1 3 | \_\_\_\_\_ 80

1 4 | \_\_\_\_\_ 80

1 5 | FACILITY STATUS [E] (28) | % POWER [0] [8] [0] (29) | OTHER STATUS [N/A] (30) | METHOD OF DISCOVERY [B] (31) | DISCOVERY DESCRIPTION [Operator Observation] (32)

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE [Z] (33) [Z] (34) | AMOUNT OF ACTIVITY [N/A] (35) | LOCATION OF RELEASE [N/A] (36)

1 7 | PERSONNEL EXPOSURES NUMBER [0] [0] [0] (37) | TYPE [Z] (38) | DESCRIPTION [N/A] (39)

1 8 | PERSONNEL INJURIES NUMBER [0] [0] [0] (40) | DESCRIPTION [N/A] (41)

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) | DESCRIPTION [N/A] (43)

2 0 | PUBLICITY ISSUED [N] (44) | DESCRIPTION [S] (45) | 8211290770 821110 PDR ADOCK 05000334 S PDR

NRC USE ONLY

Attachment To LER 82-045/03L  
Beaver Valley Power Station  
Duquesne Light Company  
Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.