

LICENSEE EVENT REPORT (CAR 1408)

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 NYREG 1200-0000G-00034111145

CON'T REPORT SOURCE L605000244710168281115829

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On 10-16-82 an operator on tour of the Auxiliary Building noticed leakage from the 1B Component Cooling Water Pump discharge vent piping. Upon further investigation, the nipple attached to the discharge pipe broke off. The 1B CCW Pump was removed from service and declared inoperable. This is a limiting condition for operation based on Tech Spec 3.3.3.2 and is reportable based on Tech Spec 6.9.2b(2).

09 WB11 E12 D13 PIPPEXX14 A15 Z16 17 LER/RO REPORT NUMBER 82 023 03 22 23 24 26 27 28 29 30 31 32 33 A18 Z19 Z20 Z21 0000 N23 N24 A25 B13026

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The failed pipe was replaced with a steel schedule 80 nipple. The apparent cause of the failure has been attributed to personnel error, i.e.: a person stepping on the nipple. This has not been verified and is still under investigation tracked by CAR 1408.

15 G28 000029 NA 30 31 A31 Aux. Operator Tour 32

16 Z33 Z34 NA 35 NA 36

17 00037 Z38 NA 39

18 00040 NA 41

19 Z42 NA 43

20 N44 NA 45 8211290771 821115 PDR ADOCK 05000244 S PDR