JAN 25 1994

Docket Nos. 030-01244 030-33300 License Nos. 06-00819-03 06-00819-04

Yale-New Haven Hospital ATTN: Norman G. Roth Vice President of Administration 20 York Street New Haven, Connecticut 06504

Dear Mr. Roth:

Subject: Routine Inspection Nos. 030-01244/93-003 and 030-33300/93-001

This letter refers to your December 20, 1993 correspondence, in response to our November 3, 1993 letter.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

No reply to this letter is required. Thank you for your cooperation in this matter.

Sincerely,

Original Signed By: Jenny M. Johansen

Jenny M. Johansen, Chief Medical Inspection Section Division of Radiation Safety and Safeguards

1E.07 \

CC:

9402220157 9401

Public Document Room (PDR) Nuclear Safety Information Center (NSIC) State of Connecticut

180057

OFFICIAL RECORD COPY - S:\PENDING\YALENEW.RL - 01/18/94

REGION I

Yale-New Haven Hospital

bcc:

Region I Docket Room (w/concurrences)

DRSS RI

Dwyer/cmm

1/24/94

DRSS:RI Johansen

1/21

OFFICIAL RECORD COPY - S:\PENDING\YALENEW.RL - 01/18/94



20 York Street, New Haven, CT 06504

Radiological Physics - WW 204

Docket Nos.: 030-1244 030-33300

License Nos.: 06-00819-03 06-00819-04

December 20, 1993

Jenny M. Johansen, Chief Medical Inspection Section Division of Radiation Safety and Safeguards U. S. Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, PA 19406

Dear Ms. Johansen:

Subject: Reply to Notice of Violation, Dated November 3, 1993, Relating to Routine Inspection Nos. 030-01244/93-003 and 030-33300/93-001

Yale-New Haven Hospital has taken the following actions to correct the apparent violation noted in the NRC inspection conducted by James P. Dwyer, on September 27 - 30, 1993.

The procedures for monitoring patients after High Dose Rate (HDR) afterloading therapy have been modified. While all HDR patients were being monitored in the past, records of these surveys were not being kept in accordance with the requirements of 10 CFR 35.404(a). The HDR afterloading therapy forms have been modified to include a survey record which includes the patient name, the dose rate at 1 meter in millirem per hour, the survey instrument used and the initials of the individual who made the survey. Full compliance with the requirements of 10 CFR 35.404(a) were accomplished by October 15, 1993.

This completes the hospital's response to the Notice of Violation. If there are any further questions regarding this matter, please contact the Radiation Safety Officer at (203) 785-2950.

Sincerely,

Michael J. Bohan Health Physicist/ Radiation Safety Officer

cc: Robert C. Lange, Ph.D., Chairman, Radiation Safety Committee Ravinder Nath, Ph.D., Director, Radiological Physics Norman G. Roth, Vice President, Administration