

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M I D C I C 2 | 2 | 0 0 - 0 0 0 0 0 - 0 0 | 3 4 | 1 1 1 1 | 4 | _____ | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT
0 1 | R E P O R T S O U R C E | L | 6 | 0 5 0 0 0 0 3 1 6 | 7 | 1 0 2 7 8 2 | 8 | 1 1 2 4 8 2 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | DURING AN AUTOMATIC ACTUATION OF THE CO2 FIRE PROTECTION SYSTEM IN THE AUXILIARY
0 3 | CABLE VAULT, FIRE DAMPER 2-HV-ACES-1 FAILED TO CLOSE. THIS CONSTITUTED AN INOPERABLE
0 4 | PENETRATION FIRE BARRIER PER T.S. 3.7.10. THE ACTION REQUIREMENTS WERE MET. PUBLIC
0 5 | HEALTH AND SAFETY WERE NOT AFFECTED. THIS WAS THE FIRST OCCURRENCE OF THIS TYPE.
0 6 | _____
0 7 | _____
0 8 | _____
0 9 | _____
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

0 3 | SYSTEM CODE | A B | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | X X X X X X | 14 | COMP SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 | LER/RO REPORT NUMBER | 8 2 | 21 22 | SEQUENTIAL REPORT NO. | 0 8 9 | 24 25 26 | OCCURRENCE CODE | 0 3 | 27 28 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 31 32
ACTION TAKEN | B | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 0 0 0 | 22 23 24 25 | ATTACHMENT SUBMITTED | N | 26 | NPD-4 FORM SUB. | N | 27 | PRIME COMP. SUPPLIER | A | 28 | COMPONENT MANUFACTURER | X 9 9 9 | 29 30 31 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | THE CO2 ACTIVATED RELEASE DEVICE FOR THE DAMPER OPERATED CORRECTLY. HOWEVER THE
1 1 | GUILLOTINE DOOR DID NOT CLOSE. THE DOOR WAS BOUND IN THE TRACK BECAUSE OF A DENT
1 2 | IN THE DOOR. THE DOOR WAS STRAIGHTENED, REALIGNED AND FUNCTIONALLY TESTED. CAUSE
1 3 | OF THE DENT IS UNKNOWN. THE DAMPER HAD FUNCTIONED SATISFACTORILY WHEN TESTED IN
1 4 | MAY, 1982.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 5 | FACILITY STATUS | E | 28 | % POWER | 1 0 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | INSPECTION FOLLOWING CO2 ACTUATION | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 5 | ACTIVITY CONTENT | Z | 33 | AMOUNT OF ACTIVITY | NA | 34 | LOCATION OF RELEASE | NA | 35
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 7 | PERSONNEL EXPOSURES | 0 0 0 | 37 | Z | 38 | DESCRIPTION | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 8 | PERSONNEL INJURIES | 0 0 0 | 40 | DESCRIPTION | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 9 | LOSS OF OR DAMAGE TO FACILITY | Z | 42 | DESCRIPTION | NA | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 9 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

8212060057 821124
PDR ADOCK 05000316
S PDR

NRC USE ONLY

NAME OF PREPARER DAVID G. WIZNER PHONE 616-465-5901