U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-346/82-30(DETP)

Docket No. 50-346

License No. NPF-3 Safeguards Group IV

Licensee: Toledo Edison Company

Edison Plaza

300 Madison Avenue Toledo, OH 43652

Facility Name: Davis-Besse Nuclear Power Station, Unit 1

Inspection At: Davis-Besse Site, Oak Harbor, OH

Inspection Conducted: October 25-29, 1982

Date of Last Physical Security Inspection: May 17-21, 1982

Type of Inspection: Routine, Unannounced Physical Protection

Inspectors: S. S. Pittle
G. L. Pirtle

Physical Protection Specialist

J.R. Kniceley

Physical Protection Specialist

11/23/82 Date

Approved By: J. R. Creed, Chief Safeguards Section

Inspection Summary

Inspection on October 25-29, 1982 (Report No. 50-346/82-30(DETP)) Areas Inspected: Included a review of Security Organization - Management, Personnel, and Response; Records and Reports; Testing and Maintenance; Physical Barriers - Vital Areas and Protected Areas; Access Controls -Personnel, Packages, and Vehicles; Detection Aids - Vital Areas and Protected Areas; Safeguards Contingency Plan; Guard Training and Qualification Plan; Followup on Previous Items of Noncompliance; and Independent Inspection Effort. The inspection involved 74 inspector-hours onsite by two NRC inspectors. The inspection began during the day shift period; 16 of the 74 inspector-hours were accomplished during offshift periods.

8212060080 821129 PDR ADDCK 05000346

Enclosure Contains SAFEGUARDS INFORMATION Upon Separation This Page is Decontrolled

Results: The licensee was found to be in compliance with NRC requirements within the areas examined during this inspection except for the following two items:

- Security Organization Personnel: A security Officer performed duties without being fully qualified in one aspect of the duty. (Paragraph 7.a)
- 2. Access Control Personnel: Protected area badges on one observed occasion were not issued in accordance with the licensee's procedure. (Paragraph 13.a)

Two items of noncompliance noted in the previous inspection were closed. All areas of concern noted in the previous inspection were closed. An area of concern pertaining to maintenance support for certain security equipment was noted during this inspection. The licensee's commitments pertaining to the area of concern appeared adequate to resolve the issue.

(DETAILS - UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled