

RECEIVED NRC

SACRAMENTO MUNICIPAL UTILITY DISTRICT 

6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

1982 NOV 29 PM 12: 41

November 19, 1982

REGION YIS

R H ENGELKEN, REGIONAL ADMINISTRATOR
REGION V OFFICE OF INSPECTION AND ENFORCEMENT
U S NUCLEAR REGULATORY COMMISSION
1450 MARIA LANE SUITE 210
WALNUT CREEK CA 94596

DOCKET NO. 50-312 LICENSE NO. DPR-54 LICENSEE EVENT REPORT NO. 82-25 SUPPLEMENT

In accordance with Rancho Seco Technical Specifications Appendix B sections 2.5 and 5.b.2.C, the Sacramento Municipal Utility District hereby submits a supplement to Licensee Event Report No. 82-25, originally reported on September 17, 1982. This paragraph provides the documentation of the applicable Technical Specification sections that were omitted in the original submittal.

On September 8, 1982, the monthly California Water Quality Board review detected oxygen levels below Technical Specification limits downstream in the Hadselville Creek. This low oxygen level was obtained in a sample of water for irrigation by downstream farmers.

The analyst responsible for sampling has been instructed to sample downstream of the impoundment if the oxygen level is <5 ppm downstream of the site boundary.

There were no effects on plant or public safety by this event.

John J. Mattimoe General Manager

cc: DCD, Washington

INPO