

ENCLOSURE 1

NOTICE OF VIOLATION

Entergy Operations, Inc.
Grand Gulf

Docket No.: 50-416
License No.: NPF-29

During an NRC inspection conducted on January 10 - 28, 1994, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," the violation is listed below:

10 CFR 50 Appendix B, Criterion XVI, requires that measures shall be established to assure that conditions adverse to quality, such as malfunctions and deficiencies are promptly identified and corrected. 10 CFR 50 Appendix B is implemented by the Quality Assurance Topical Report, GGNS-TOP-1A. Section 16.5.2 of the Topical Report requires that procedures shall provide for the evaluation of conditions such as malfunctions and deficiencies. Section 16.5.3 of the Topical Report requires follow-up reviews by the appropriate organizations to verify proper implementation of the corrective action.

Contrary to the above:

- (1) On July 15, 1993, the licensee became aware, or should have been aware, that four safety-related breaker close coils may have been subjected to operating conditions beyond their rating, during license testing but this condition was not evaluated. The breaker close coils involved were for Divisions I and II emergency diesel generator output breakers, Division I RHR pump motor breaker and Division I drywell purge compressor motor.
- (2) In 1983, during preoperational testing the licensee identified a design problem with the control circuit for the safety-related drywell purge compressors that could defeat or degrade the function of the safety-related Drywell Purge System and prepared a modification to correct the problem, but the modification was not implemented until November, 1993, after the circuit actually malfunctioned during performance of a test.

This is a Severity Level IV violation (Supplement 1).

Pursuant to the provisions of 10 CFR 2.201, Entergy Operations, Inc. is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved,

Entergy Operations, Inc.
Grand Gulf

2

Docket No.: 50-416
License No.: NPF-29

(3) the corrective steps that will be taken to avoid further violations, and
(4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Atlanta, Georgia
this 15th day of February 1994