

71374

LOCKETED  
USNRC

January 29, 1991

'91 JAN 30 AM 1:33

UNITED STATES OF AMERICA  
NUCLEAR REGULATORY COMMISSION

OFFICE OF SECRETARY  
DOCKETING & SERVICE  
BRANCH

before the

ATOMIC SAFETY AND LICENSING BOARD

In the Matter of  
  
PUBLIC SERVICE COMPANY  
OF NEW HAMPSHIRE, et al.  
  
(Seabrook Station, Units 1  
and 2)

Docket Nos. 50-443-OL  
50-444-OL

(Offsite Emergency  
Planning Issues)

MEMORANDUM

It has come to our attention that in certain copies of  
"Licensees' Response to Memorandum and Order of January 24, 1991"  
Global Page No. 0000082 was inadvertently omitted. A copy of  
that page is enclosed herewith for the records of those whose  
copy is missing that page.

  
Thomas G. Dignan, Jr.

6.3 PLANT STATUS INFORMATION AND PROTECTIVE  
ACTION RECOMMENDATIONS

Figures (from NHY Emergency Response Procedures)

- 1 Figure 6.3-1 - Plume Exposure Protective Action Flow Chart for Site Area Emergency
- 2 Figure 6.3-2 - Plume Exposure Protective Action Flow Chart for General Emergency