

PUBLIC SERVICE INDIANA

S. W. Shields Senior Vice President -Nuclear Division

Mr. James G. Keppler Regional Administrator U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137 December 3, 1982 S82-16 SVP-0056-82

Docket Nos.: STN 50-546 STN 50-547 Construction Permit Nos.: CPPR - 170 CPPR - 171

Marble Hill Nuclear Generating Station - Units 1 and 2

Dear Mr. Keppler:

On July 21, 1982, Mr. T. D. Geib of Public Service Company of Indiana, Inc. (PSI) notified your office of a potentially reportable item as required by 10 CFR 50.55(e). Conduit and cable tray hanger inspection reports generated by the electrical erection contractor, Commonwealth-Lord Joint Venture, were determined to have a variety of deficiencies. The deficiencies included missing inspection reports, inadequate description of items inspected, missing inspection results, and conflicting notes.

Commonwealth-Lord Joint Venture has revised inspection procedures to clarify documentation requirements. Conduit and cable tray hangers previously inspected have been reinspected to the revised procedures. Deficiencies were identified in some of the reinspected hangers and these hangers will be reworked.

If the deficient hangers had not been corrected, their structural integrity may have been reduced during design basis loadings. The revised Commonwealth-Lord Joint Venture inspection procedures will prevent the reoccurrence of these deficiencies.

This letter is intended to fulfill the requirements of a final report as required by 10 CFR 50.55(e). If you have any questions regarding this report, please feel free to contact me.

Sincerely,

S. W. Shields

DEC 6 1982

IEZT

8212100181 821203 PDR ADOCK 05000546 S PDR

SWS/TDG/hft

P. O. Box 190, New Washington, Indiana 47162

812.289.1000



.

SERVICE INDIANA Letter: J. G. Keppler

-2-

December 3, 1982 S82-16 SVP-0056-82

cc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

J. E. Konklin J. J. Harrison