

LICENSEE EVENT REPORT

Attachment to AECM-82/588
Page 1 of 1

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 34 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT EB

CON'T
01 L 6 0 5 0 0 0 4 1 6 7 1 1 0 8 8 2 8 1 2 0 7 8 2 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 | A smoke detector in the zone covering the control building elevation 166 feet and
03 | 177 feet alarmed and would not reset. Investigation revealed no smoke or fumes
04 | present in the area. A fire watch was established pursuant to T.S.3.3.7.9. There
05 | was no effect on the health and safety of the public. This event did not constitute
06 | a threat to plant safety.
07 |
08 |

09 A B 11 X 12 Z 13 I N S T R U 14 E 15 Z 16
9 10 11 12 13 18 19 20
17 8 2 1 1 4 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32
C Z Z Z 0 0 0 0 N N A H 2 6 0
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 | The continuous alarm resulted from damage to the detector due to insulation work in
11 | the area. The damaged detector was replaced with a new one. The new detector was
12 | tested and placed in service on November 9, 1982. This report is final pursuant
13 | to T.S.6.9.1.13.b.
14 |

15 B 28 0 0 0 29 NA 30 A 31 Alarmed Condition 32
7 8 9 10 12 13 44 45 46 80
16 Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 44 45 80
17 0 0 0 37 Z 38 NA 39
7 8 9 11 12 13 80
18 0 0 0 40 NA 41
7 8 9 11 12 80
19 Z 42 NA 43
7 8 9 10 80
20 N 44 8212100306 821207
7 8 9 10 11 12 68 69 80
PDR ADDCK 05000416
S PDR