



December 10, 1982
L-82-538

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

RE: ST. LUCIE UNIT 2
DOCKET NO. 50-389, 10 CFR 50.55(e), 82-023
MICRO-SWITCH PTK SELECTOR SWITCHES

On November 10, 1982, Florida Power and Light Company (FPL) notified the Region II Office of Inspection and Enforcement, in accordance with the requirements of 10 CFR 50.55(e), of a potential deficiency regarding the failure of micro-switch PTK selector switches. FPL is still reviewing this problem and will submit a final report by January 10, 1983.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems and Technology

REU/ok

cc: Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

RECEIVED
DEC 11 1982
REGION II

8212210354 821210
PDR ADOCK 05000389
S PDR

OFFICIAL COPY
LE 27