APPENDIX

NOTICE OF VIOLATION

Radiclogy of Eastern Oklahoma, Inc. Tulsa, Oklahoma

Docket No. 030-02925/91-01 License No. 35-13341-01

During an NRC inspection conducted on January 7, 1991, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1990), the violation is listed below:

10 CFR 35.50(c) requires, in part, that the licensee shall perform dose calibration geometry dependence tests required by Section 35.50(b)(4) following adjustment or repair of the dose calibrator.

Contrary to the above, the licensee failed to perform the required dose calibrator geometry test on the licensee's Searie Analytic-Mediac Model 6362 (Serial Number 004304) dose calibrator after the dose calibrator was repaired and returned to service between June and August 1988, and prior to patient dose checks being performed.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Radiology of Eastern Oklahoma, Inc., is hereby required to submit to this office, within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation: (1) the reason for the violation if admitted, (2) the corrective steps which have been taken and the results achieved, (3) the corrective steps which will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas, this 28th day of January 1991