01 BAXLEY, GA. 31513 PMS MR. JAMES P. O'REILLY RC REGION UNITED STATES NUCLEAR REGULATORY COMMISSION TA, GEORGIA DIRECTOR OF INSPECTION AND ENFORCEMENT REGION II 81 DEC 17 A8 . 1" SUITE 3100 101 MARIETTA STREET ATLANTA, GEORGIA 30303

SUBJECT: HATCH UNIT II, DOCKET NO. 50-366, NOTIFICATION OF REPORTABLE OCCURRENCE NO. 50-366/1981-124

NOTIFIED: Mr. Austin Hardin

12-16-81 DATE:

DATE:	12-16-81
TIME:	1440 CST

DESCRIPTION OF REPORTABLE OCCURRENCE

#### Initial Condition

At the time of occurrence, December 15, 1981 at 0745 CST. Anit IEECEWED was in normal operation at 97% power. DEC 2 3 1981

#### Nature of Occurrence

A fire main had ruptured on the southwest side of the plant. The leak was isolated and a review of inoperative fire protection systems. was in progress. The review revealed that the east header had been previously isolated to repair a leak (leak had been repaired but not released for use).

This caused fire water to be isolated to Reactor Building and Turbine Building requiring a continuous fire watch with backup fire suppression equipment for the unprotected areas within one hour.

## Immediate Corrective Action

Clearances were immediately released on east supply header and it was returned to service.

#### Cause

Due to the large number of systems isolated, it was determined that the quickest method of restoring protection was to place the east header back in service. This header was returned to service and all systems back in service within three hours.

REGIONAL DIRECTOR DEPUTY DIRECTOR ASSISTANT TO DIRECTOR DIRECTOR, RRPL analan kanan ka Kanan kana

Page 1 of 2

B112240166 B11216 PDR ADOCK 05000366

DIRECTOR, ENF/INV DIRECTOR, ETI PUBLIC AFFAIRS OFFICER

# Supplemental Corrective Action

A more positive control means will be developed to track fire system outages.

Status of Redundant or Backup Systems

No backup systems available

## Impact to Other Units

None

## Justification for Continued Operation

Fire protection requirements are now fully in compliance.

ant Mana

Page 2 of 2