

518

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

December 17, 1981

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

USNRC REGION II  
ATLANTA, GEORGIA  
31 DEC 21 4 9: 01

Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCY -  
ROSEMOUNT MODEL 1152 AND 1151 PRESSURE TRANSMITTER DEFECTS  
(NCR PRC 80-28)

Initial notification of the subject deficiency was made to NRC-OIE, Region II, Inspector R. W. Wright on June 3, 1980. The first, second, third, and fourth interim reports of the subject deficiency were submitted on July 2, September 17, 1980, April 3, and June 30, 1981, respectively. In compliance with paragraph 50.55(e) of 10 CFR Part 50, this letter constitutes the fifth interim report of the subject deficiency.

TVA is still in the process of investigating use of the subject transmitters. A more detailed report of this investigation will be provided on or before June 22, 1982. If you have any questions, please call Jim Domer at FTS 858-2725.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*L. M. Mills*

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. R. C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555



8112240167 811217  
PDR ADOCK 05000518  
S PDR

IE 27  
56  
OFFICIAL COPY