

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [S] [I] [C] [N] [E] [E] [2] [2] [0] [0] [-] [0] [0] [0] [0] [0] [-] [0] [0] [3] [4] [1] [1] [1] [1] [4] [] [] (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 23 28 LICENSE TYPE 30 37 CAT 38

CONT [0] [1] REPORT SOURCE [L] [5] [0] [5] [0] [0] [0] [2] [7] [0] [7] [1] [1] [2] [4] [8] [1] [8] [1] [2] [0] [8] [8] [1] [9]
7 8 90 DOCKET NUMBER 98 99 EVENT DATE 174 175 REPORT DATE 180

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[3] [2] On November 24, 1981, construction personnel severed a 2 inch line which
[3] [3] branched off the water header supplying the CT-5 transformer fire suppression
[3] [4] system. The suppression system was isolated, and a fire watch and backup fire
[3] [5] suppression equipment were not provided as required by Technical Specification
[3] [6] 3.1.7.3.1. The transformer CT-5 is a redundant emergency power supply, and the
[3] [7] loss of the suppression system did not affect the operability of the trans-
[3] [8] former; thus the health and safety of the public were not affected by this event.

[3] [9] SYSTEM CODE [A] [B] (11) CAUSE CODE [X] (12) CAUSE SUBCODE [Z] (13) COMPONENT CODE [V] [A] [L] [V] [E] [X] (14) COMP SUBCODE [E] (15) VALVE SUBCODE [D] (16)
17 LEAD REPORT NUMBER [18] [1] [1] (21) SEQUENTIAL REPORT NO. [0] [1] [9] (24) OCCURRENCE CODE [0] [1] (27) REPORT TYPE [T] (30) REVISION NO. [0] (32)
ACTION TAKEN [X] (18) ACTION [X] (19) EFFECT ON PLANT [R] (20) SHUTDOWN METHOD [Z] (21) HOURS [0] [0] [0] [1] (22) ATTACHMENT SUBMITTED [Y] (23) APPROX FORM BUS [N] (24) PRIME COMP SUPPLIER [L] (25) COMPONENT MANUFACTURER [M] [10] [10] [3] (26)
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (37)

[1] [3] The cause of this incident is currently being investigated and will be
[1] [1] reported in a revision to this report. Corrective action was to commence shut-
[1] [2] down of Oconee 1 and 2, establish backup fire protection capability, and
[1] [3] secure the unit shutdown, the leak was repaired and the fire suppression
[1] [4] system returned to service.

[1] [5] FACILITY STATUS [E] (28) % POWER [0] [7] [5] (29) OTHER STATUS NA (30) METHOD OF DISCOVERY [A] (31) DISCOVERY DESCRIPTION operator observation (32)
[1] [6] ACTIVITY CONTENT [Z] (33) AMOUNT OF ACTIVITY NA (35) LOCATION OF RELEASE NA (36)
[1] [7] PERSONNEL EXPOSURES NUMBER [0] [0] [0] (37) TYPE [Z] (38) DESCRIPTION NA (39)
[1] [8] PERSONNEL INJURIES NUMBER [0] [0] [0] (40) DESCRIPTION NA (41)
[1] [9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION NA (43)
[2] [0] PUBLICITY ISSUED [N] (44) DESCRIPTION NA (45) NRC USE ONLY

NAME OF PREPARER J. F. Kutzer PHONE: (704) 373-7139
8112240254 811208
PDR ADDCK 05000270
S PDR