

March 9. 1983

Mr. James G. Keppler Regional Director Office of Inspection and Enforcement Region III U. S. Nuclear Regulatory Commission Glen Ellyn, Il. 60137

Reference: Zion Generating Station

Docket No. 50-304/DPR-48

Technical Specification, Section 6.6.2

Dear Mr. Keppler:

The enclosed Licensee Event Report from Zion Generating Station is being transmitted to you in accordance with the requirements of Technical Specifications, 6.6.2a (5) This section states a fourteen day written report is required when failure or malfunction of one or more components which prevents or could prevent, by itself, the fulfillment of the functional requirements of system(s) used to cope with accidents analyzed in the SAR. This report is number 83-007/01 T-0, Docket No. 50-304/DPR-48.

Prompt notification has been made to Region III, Directorate of Regulatory Operations by telephone on 2/1/83 and by teletype on 2/2/83.

This event was reclassified to a 14 day reportable occurrence on 2-1-83 therefore the telephone/teletype notifications were made outside the required time after the event, but within the required time after reclassification.

This event was previously reported as a unit 1 event on Licensee Event Report 50-295/83-002/01 T-0, dated 02-10-83 which has been cancelled.

> Superintendent Zion Station

Enclosure: Reportable Occurrence Report No. 83-007/01 T-0; 50-304

KLG/ss

cc: J. Waters, NRC Resident Inspector