

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

32 FEB 18 P 1: 24

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

February 12, 1982

TELEPHONE: AREA 704  
373-4083


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Catawba Nuclear Station  
Units 1 and 2  
Docket Nos. 50-413 and 50-414

Dear Mr. O'Reilly:

In my September 26, 1980 letter which transmitted Significant Deficiency Report SD 413-414/80-13 concerning improper operation of an optical isolator, it was stated that all corrective actions would be complete by January 1, 1982. Due to difficulty in obtaining replacement components from the vendor, the change out of all affected isolators will now be accomplished by January 1, 1983.

Very truly yours,

  
William O. Parker, Jr

RWO/php

cc: Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. P. K. Van Doorn  
NRC Resident Inspector  
Catawba Nuclear Station

Mr. Robert Guild, Esq.  
Attorney-at-Law  
314 Pall Mall  
Columbia, South Carolina 29201

Palmetto Alliance  
2135 1/2 Devine Street  
Columbia, South Carolina 29205

