

USNRC REGION II
ATLANTA, GEORGIA

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

12 FEB 25 P 1: 50
WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

February 23, 1982

TELEPHONE: AREA 704
373-4083

Mr. J. P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

With regards to Reportable Occurrence Report RO-369/81-181 submitted by my letter dated January 19, 1982, in addition to the steps outlined in the report, Duke Power Company has taken the following additional corrective action: Control Room Operators will be instructed to be more detailed in recording Technical Specification items in the log. Operators will now be required to log the exact reason a system (or piece of equipment) required by Technical Specifications is removed from or returned to service. This should eliminate any confusion among the operators as to the exact status of Technical Specification related equipment.

Very truly yours,

William O. Parker, Jr.
William O. Parker, Jr.

PBN/jfw

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector-NRC
McGuire Nuclear Station

8203080257 820223
PDR ADOCK 05000369
S PDR

OFFICIAL COPY

FE 22 51/0