LICENSEE EVENT REPORT

	강인 사는 그는 것이 그렇게 되는 그들은 그들이 마시아 아름이 되었어요? 그렇게 되는 것은 사람들이 되었다면 하는 것이 없다면
	CONTROL SLOCK:
0 ;	F L S L S 1 2 0 0 - 0 0 0 0 0 0 0
CON'T	AEPORT L 6 0 5 0 0 0 3 3 5 7 0 8 2 7 8 2 0 0 9 1 3 8 2 9 .
0 2	During full power operation, the IA startup transformer was taken out of
0 3	service for maintenance. The surveillance requirements of Tech Spec 3.8.1.1
3 4	were performed prior to this except for verifying operability of the 1B
0 5	diesel generator. This is reportable in accordance with Tech Spec
0 6	6.9.1.9.c. The health and safety of the public were not affected.
0 7	
0 3	
7 3	SYSTEM CAUSE CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE E E 11
, 8	9 10 11 12 13 18 19 20 20 SEQUENTIAL OCCUPARENCE SECRET
	1) REPORT NUMBER 8 2 - 0 3 9 0 3 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP COMPONENT WANUFACTURER LT 13 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 Z 26 Z 9 9 9 9 2
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	The oversight was discovered 1.5 hours after the start up transformer was
	removed from service. The start up transformer was being returned to ser-
1 2	vice at that time. The 1B diesel was verified to be operable. Personnel
1 3	have been instructed to insure all Tech Spec requirements have been met
1 4	prior to taking a piece of equipment out of service.
15	ACILITY OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
	LEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (26) NA
	PERSONNEL EXPOSURES O VUMBER OLO TYPE DESCRIPTION (39)
7 3	3 25 11 12 13 30 30
1 3	O O O O O O O O O O O O O O O O O O O
,	CSS OF DR DAMAGE TO FACILITY (43)
7 3	Z (42) NA
2 0	NAC USE ONLY NAC USE ONLY NA
7 3	P. L. Pace (305) 552-3654
	NAME OF PREPARER T. L. FACE