LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 7 CAT 58
CON'T O 1 SOURCE L 6 0 5 00 0 2 7 2 7 0 7 3 1 8 2 8 0 9 0 3 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 At 0112 hours, July 31, 1982, a leak was discovered from a flexible hose to No. 1C
0]3 Diesel Generator (DG) Cooling Water Jacket. No. 1C DG was declared inoperable and
0 4 Action Statement 3.8.1.1a was entered.
0 5
0 6
0 7
0 8 0
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUB
1 0 The cause of this occurrence was deterioration of the rubber hose wall meterial due
to age. The failed flexible hose was replaced and tested satisfactorily. At 0130
hours, August 1, 1982, No. 1C Diesel Generator was declared operable, and Action
Statement 3.8.1.la was terminated. New flexible hoses will be installed as needed
on the diesel generators at the next refueling outage.
1 5 E 28 0 9 9 29 N/A A 31 Operational Event 80 80 80 80 80 80 80 8
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 Z (33) Z (34) N/A LOCATION OF RELEASE (36) N/A LOCATION OF RELEASE (36) N/A M/A SERVICE SERV
1 7 0 0 0 37 Z 38 N/A 7 8 9 PERSONNEL INJURIES 13 80
1 B O O O O O O N/A
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A PDR ADDCK 05000272 NOCHECOLOGY NOCHECOL
ISSUED DESCRIPTION (45) N/A
NAME OF PREPARED R. Frahm PHONE: 609/935-6000 Ext. 3078 0