

APPENDIX A
NOTICE OF VIOLATION

Department of the Air Force
Eglin Air Force Base

License No. 09-17214-01

As a result of the inspection conducted on January 4, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

License Condition 15 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in application dated September 1, 1981.

1. Block 10 of this application requires that the dose calibrator be checked quarterly for linearity of response and that records be kept of the results.

Contrary to the above, records of quarterly linearity checks have not been maintained as required since June 1980.

2. Block 14 of this application requires that certain procedures be followed for safely opening packages containing radioactive materials.

Item 2.f of Appendix F Regulatory Guide 10.8, requires that each package of radioactive material be surveyed for contamination by swiping the external surface of the final source container.

Contrary to the above, individual packages of iodine-131 received in the Nuclear Medicine Department have not been surveyed for removable contamination as required.

This is a Severity Level V Violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: JAN 27 1983

8303210500 830225
NMS LIC30
09-17214-01 PDR