

DONALD C. COOK NUCLEAR PLANT P.O. Box 458, Bridgman, Michigan 49106 (616) 465-5901

March 14, 1983

Mr. J.G. Keppler, Regional Administrator United States Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

Operating License DPR-58 Docket No. 50-315

Dear Mr. Keppler:

This is to confirm a verbal report made by Mr. B.A. Svensson, Assistant Plant Manager, to your Mr. E.R. Swanson, Senior Resident Inspector at the Donald C. Cook Nuclear Plant, on March 11, 1983, at 1615 hours. At that time Mr. Svensson advised Mr. Swanson that during an inspection of the D.C. Cook Plant fire doors, a fire door (#469) in the Unit 1 Boron Injection Tank Room was found that did not have a label to substantiate UL certification. The Plant's immediate action was to post a continuous fire watch for this door.

As required by Technical Specification 6.9.1.8, a followup report will be submitted within 14 days.

Sincerely,

For W.G. Smith, Jr.
Plant Manager

/bab

cc: J.E. Dolan

R.S. Hunter

M.P. Alexich

R.F. Kroeger

B. Germano

E.R. Swanson/N.E. DuBry

R.C. Callen MPSC

G. Charnoff, Esq.

J.M. Hennigan

R.O. Bruggee EPRI

INPO

**PNSRC** 

J.F. Stietzel

E.L. Townley

Dir., IE (40 copies)

Dir., MIPC (4 copies)

MAR 17 1983