LICENSEE EVENT REPORT

EXHIBIT A

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	0 R T N P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 57 CAT 58
CON'T	SOURCE L 6 0 5 0 - 0 3 4 4 7 0 8 1 9 8 2 8 0 9 1 7 8 2 9
9 2	DURING A POST-MAINTENANCE CHECK ON PSV-8010C PRESSURIZER SAFETY VALVE, IT
0 3	WAS DISCOVERED THAT THE LIFT SETPOINT EXCEEDED THE TOLERANCE LIMIT
0 4	ADDRESSED IN TECHNICAL SPECIFICATION 3.4.3.1 WHEN THE VALVE WAS REQUIRED
0 5	TO BE OPERABLE. THIS EVENT HAD NO EFFECT ON EITHER PLANT OR PUBLIC SAFETY
0 6	SINCE THE OTHER SAFETY VALVES WERE OPERABLE AND NO OVERPRESSURE TRANSIENT
0 7	OCCURRED.
08	
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	COMPONENT COMP
10	THIS OCCURRENCE RESULTED FROM A SMALL ERROR IN BENCH SAFETY VALVE LIFT
11	POINT SETTING BEING DISCOVERED DURING TESTING IN A PLANT MODE FOR WHICH
1 2	THE SAFETY VALVE MUST BE OPERABLE. SAFETY VALVE WAS IMMEDIATELY RESET TO
13	TECHNICAL SPECIFICATIONS CRITERIA.
14	
	STATUS STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA B 31 POST-MAINTENANCE CHECK
	CITIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA NA 12 13 44 46 46 46 NA NA
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA
1 8	NUMBER DESCRIPTION 41 NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43 LZ 42 NA
20	PUBLICITY SSUED DESCRIPTION 45 NAC USE ONLY NA
7 8	NAME OF PREPARER Gary G. Bair (FJU) PHONE: 503/556-3713 Extension 234