

SACRAMENTO MUNICIPAL UTILITY DISTRICT 

6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

31 NI 12 20

September 17, 1982

R H ENGELKEN, REGIONAL ADMINISTRATOR
REGION V OFFICE OF INSPECTION AND ENFORCEMENT
U S NUCLEAR REGULATORY COMMISSION
1450 MARIA LANE SUITE 210
WALNUT CREEK CA 94596

DOCKET NO. 50-312 LICENSE NO. DPR-54 LICENSEE EVENT REPORT NO. 82-25

On September 8, 1982, the monthly California Water Quality Board Review detected oxygen levels below Technical Specification limits downstream in the Hadselville Creek. This low oxygen level was obtained in a sample from an area that was stagnant due to downstream farmers impoundment of water for irrigation.

The analyst reponsible for sampling has been instructed to sample downstream of the impoundment if the oxygen level is <5 ppm downstream of the site boundary.

There were no effects on plant or public safety by this event.

John J Mattimoe General Manager

Attachment

cc: DCD, Washington

INPO

8209280105 820917 PDR ADOCK 05000312 S PDR