



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

RECEIVED
100

SEP 21 PM 12 27

September 15, 1982

R H ENGELKEN, REGIONAL ADMINISTRATOR
REGION V OFFICE OF INSPECTION AND ENFORCEMENT
U S NUCLEAR REGULATORY COMMISSION
1450 MARIA LANE SUITE 210
WALNUT CREEK CA 94596

DOCKET NO. 50-312
LICENSE NO. DPR-54
LICENSEE EVENT REPORT NO. 82-24

In accordance with Rancho Seco Nuclear Generating Station Technical Specifications, Section 6.9.4.2.c, and Regulatory Guide 1.16, Section C.2.b(3), the Sacramento Municipal Utility District hereby submits a 30-day report of Licensee Event Report No. 82-24.

On August 18, 1982, it was reported that supports for a Class I cable raceway were cut back and temporary supports attached to permit access for new cable trays being run in the area. It appears that on July 19, 1982, supports H-983 and H-984 were cut back. Apparently, the foreman in the area believed that this was acceptable. Work in this area was completed on August 11, and a construction inspector noticed the temporary supports on August 13. Up to this time, the plant was in cold shutdown. The design engineer was notified of the problem, the NCR dispositioned, and a permanent fix was begun on the 18th. Work was completed and signed off at 3:00 p.m., August 19th. During the period from July 19th to August 19th, therefore, the raceway's support did not have seismic calculations or details to justify these supports.

Subsequent corrective action was to inform all Electrical General Foremen and Electrical Foremen that they must have a specific Work Request to remove or relocate any existing raceways, supports, braces, or other items affecting the safety of the plant.

A review of the raceway's circuit contents shows that only channel B safeguards were located in the tray. Attached is a list of affected circuits.

The Management Safety Review Committee will consider this event at their next meeting. A follow-up report to this LER will be provided when the District's investigation of this matter is complete. This report will provide additional details.


8209280323 820915
PDR ADDCK 05000312
S PDR

DE-29

R H Engelken, Regional Administrator
September 15, 1982

Page 2

Since the unit was in cold shutdown and only one channel of safeguards was affected, there was no effect on plant or public safety.



John J. Mattimoe
Acting General Manager

Attachment

cc: DCD, Washington
INPO